

### Delivery Order Information

Recommended Contractor	EQM, Inc.
Task Order Number	1201-9019
Amendment Number	01
Date of Order	August 12, 2015
Time of Initial Order	Sunday, 08/09/2015
OSC	Robert Wise
Date and Time Contractor Required on Site	August 11, 2015
Required Work Completion Date	October 31, 2015
Site Name	Gold King Mine R9 ER
Response Location	Navajo Nation
SSID	A998
Current Subtask Ceiling and Funding Amount	\$ 75,000
Increase	\$ 425,000
New Subtask Ceiling and Funding Amount	\$ 500,000

**Statement of Work: (The contractor shall furnish necessary paperwork, materials, services, facilities, and otherwise do all things necessary for, or incident to, the performance of the work set forth below:)**

This subtask revision 01 incrementally funds the subtask and amends the SOW to also include the following tasks:

- Conduct removal of contaminated soil from agricultural ditches, beaches, river sediment as needed.
- Provide logistics support to incident (i.e., Rent meeting space for public meetings, provide additional space for the ICP as needed.

All other requirements of the SOW remain unchanged.

**Information for Contracts Office only:**

Subtask is being incrementally funded and SOW may continue to be amended as needs continue to be assessed.

Previous SOW:

- Provide RM to perform Logistics Section Chief duties for the incident
- Provide PAS(s) to assist in Logistics
- Provide Water Replacement Services to Navajo Nation as directed by the EPA OSC.
- Provide daily 1900-55 and CERCLA Daily Work Orders
- Provide boats and support for river sampling
- Provide other technical support as directed by the EPA OSC